

CONTINGENCY AND EVACUATION PLAN
Dusty Mac Resources Inc.
Madera "24" Federal Well No. 1
Lea County, New Mexico

IV. BLOWOUT PREVENTION MEASURE DURING DRILLING AND COMPLETION (Cont'd)

D. Crew Training and Protection (Cont'd)

2. H₂S Training and Drills: (Cont'd)

Beards will not be permitted. H₂S certification card will be voided if employee wears a beard.

3. Safety Equipment:

As outlined in the Appendix, H₂S safety protection equipment will be available to/or assigned each person on location and training given in correct usage.

V. CONTINGENCY PROCEDURE

A. Responsibility:

In order to assure the proper execution of this plan, it is essential that one person be responsible for and in complete charge of implementing these procedures. The responsibility will be as follows:

1. (Dusty Mac Resources Inc.) representative or his assistant.
2. Contract toolpusher or should he become disabled, Foreman on tour.

B. Drill Site:

1. The drilling rig will be located to allow prevailing winds to blow across the rig toward the reserve pit.
2. Briefing stations will be provided with a safety equipment trailer at one or more stations. Personnel will assemble at the most up-wind station under alarm conditions, or when so ordered by the Drilling Foreman or the Safety Representative. A wind sock or streamer will be anchored to the trailer.