

CONTINGENCY AND EVACUATION PLAN

Dusty Mac Resources Inc.
Madera "24" Federal Well No. 1
Lea County, New Mexico

V. CONTINGENCY PROCEDURES (Cont'd)

B. Drill Site: (Cont'd)

A second windsock or streamer will be anchored at the end of the catwalk on a pole about 30' high so as to be in easy view of the rig floor and visible at night.

At least one Briefing Area with wind sock, will be up wind at all times.

3. H₂S warning and condition signs will be posted on the access road to the location. "NO SMOKING" signs will be posted on location and at access road.
4. Do not permit sleeping in cars on location. Maintain a parking area remote from the location preferable on the predominate upwind side of the site.
5. A gas trap, choke manifold and degasser will be installed.
6. A kill line, securely anchored and of ample strength will be laid to the well head from a safe location. This line is to be used only in an emergency.
7. All swabbing and drill stem testing fluids containing H₂S shall be run through a separator to permit flaring of gas. The flare shall have a continuous flame.
9. Provisions for blocking or monitoring access to location during critical operations.
10. The Dusty Mac Resources Inc. representative will be responsible for igniting the well if a critical condition arises.

RECEIVED

MAR 30 1994

JOSE
10/10