

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32568
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	COOPER JAL UNIT
8. Well No.	406
9. Pool Name or Wildcat	JALMAT

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.</p>	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109, MIDLAND, TX 79702
4. Well Location	Unit Letter <u>H</u> : <u>2522</u> Feet From The <u>NORTH</u> Line and <u>400</u> Feet From The <u>EAST</u> Line Section <u>24</u> Township <u>24-S</u> Range <u>36-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3303'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐ ACIDIZE & SCALE SQUEEZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-08-01: MIRU. JAR ON PUMP & WOULDN'T COME LOOSE. BACK OFF RDS. NDWH. NUBOP. RU SWAB.
 8-09-01: PU SONIC HAMMER TOOL & TIH ON 96 JTS 2 7/8" TBG. ACIDIZE PERFS USING SONIC HAMMER TOOL W/5000 GALS 15% NEFE ACID. SCALE SQUEEZE PERFS W/SONIC HAMMER TOOL.
 8-10-01: TIH W/TBG W/PINNED COLLAR, SN, & TAC. SN @ 3104'. TBG @ 3137'. NDBOP. SET TAC @ 2883. FLANGE UP WH. TIH W/PMP W/STANLEY FILTER, SNKR BARS, & RDS. SPACE OUT & HANG ON. LOAD & TEST W/500 PSI. RIG DOWN.
 9-10-01: ON 24 HR OPT. PUMPING 11 BO, 149 BW, & 7 MCF.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 9/25/01
 TYPE OR PRINT NAME J. Denise Leake Telephone No. 915-688-4752

(This space for State Use)

APPROVED PAUL F. KAUTZ TITLE PETROLEUM ENGINEER DATE OCT 11 2001
 CONDITIONS OF APPROVAL IF ANY: _____