

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32857
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	COOPER JAL UNIT
8. Well No.	410
9. Pool Name or Wildcat	JALMAT
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3324'-GR,

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>F</u> : <u>1425</u> Feet From The <u>NORTH</u> Line and <u>1450</u> Feet From The <u>WEST</u> Line Section <u>24</u> Township <u>24-S</u> Range <u>36-E</u> NMPM <u>LEA</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ ASD-RFD

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-27-98: MIRU. BLED OFF WELL. TOH W/RDS. TIH & FSH ROD BODY @ 1050-JAR OPN PUMP 25 MIN. UNABLE TO GET PUMP UNSEATED.
JARRED OFF FSH. TOH & LD RDS.
8-28-98: RU & SWAB TBG DN. NDWH. NUBOP. REL TAC. TOH W/36 JTS 2 7/8" TBG. REC FSH. REL OFF COUPLING ON TOP OF PUMP. TOH & LD RDS. TIH W/BIT ON 5 1/2" CSG SCRAPER ON 100 JTS 2 7/8" TABG TO 3020'.
8-31-98: TIH W/CIBP ON 100 JTS 2 7/8" TBG & SET @ 3000'. CIRC HLE W/75 BBLS PKR FLUID. PRESS CSG TO 500# FOR 30 MIN. WITNESSED BY BUDDY HILL W/NMOC-D-OK. TOH & LD 100 JTS 2 7/8" TBG. TIH W/BAILER ON SANDLINE. DUMP 35' CMT ON TOP OF CIBP. TOP OF CMT @ 2965'.
TOH. NDBOP. NUWH. RIG DOWN. ASD-RFD.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 9/2/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY GARY WINK TITLE FIELD REP. II

DATE SEP 15 1998