



- Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- ◇ Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAYOUT PLAT

GRUY PETROLEUM MANAGEMENT CO.
RHODES FEDERAL UNIT # 103
UNIT "P" SECTION 10
T26S-R37E LEA CO. NM