## New Mexico Oil Conservation Edvision, Unstrict I

1625 N. French Date Hobbs, NM 833

Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

## WM710374 - NMO321613

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS	SUNDRY	<b>NOTICES AND</b>	REPORTS	ON WELLS
-------------------------------------	--------	--------------------	---------	----------

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

South Mattix Unit Federa

7. If Unit or CA/Agreement, Name and/or No.

Type of Well

Name of Operator Occidental Permian Limited Partnership

9. API Well No. 35/2.3 157984

30-025-35253

Well Name and No.

3a. Address P.O. Box 50250 Midland, TX 79710-0250

Oil Well Gas Well Other

3b. Phone No. (include area code) 915-685-5717

10. Field and Pool, or Exploratory Area

Location of Well (Footage, Sec., T., R., M., or Survey Description)

towler or interned 11. County or Parish, State

2130 FAL 150 FEL SENE (H) Sec 15 TZ43

NM Lea

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other Shud, Set	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  David Stewart	Title Regulatory	Analyst	
Signature Sun Hill	Date 3\z	3 (01	
THIS SPACE FOR	FEDERAL OR STATE OFFICE U	SE	
Approved by	Title	Date	
Conditions of approval, if any, are attached. Approval of this notice doccertify that the applicant holds legal or equitable title to those rights in	es not warrant or the subject lease		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

which would entitle the applicant to conduct operations thereon.

NOTIFIED BLM 1/20/01 OF SPUD. MIRU KEY 12, SPUD WELL @ 0600hrs MST 1/20/01. DRILL 11" HOLE TO TD @ 1110', 1/20/01, PUMP SWEEP. RIH W/8-5/8" 24# J55 CSG, SET @ 1100'. M&P 300sx PREMIUM PLUS W/4% GEL + .25#/sx FLOCELE + 2% CaCl2 FOLLOWED BY 200sx PREMIUM PLUS W/2% CaCl2 + .25#/sx FLOCELE, DISP W/FW, PLUG DOWN 1/21/01, CIRC 129sx CMT TO PIT, WOC-4hrs. BLM NOTIFIED & WITNESSED. CUT OFF CASING, WELD ON WELL HEAD, TEST TO 1000#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES, & CASING TO 2500#, BLM NOTIFIED OF BOP TEST, DID NOT WITNESS.TOTAL WOC-16hrs. RIH & TAG, DRILL OUT & DRILL AHEAD 1/21/01.

DRILL 7-7/8" HOLE TO TD @ 6500', 1/31/01, PUMP SWEEP & CHC. RIH W/ OPEN HOLE LOGS, POOH. RIH W/ 5-1/2" 17# L80 CSG & SET @ 6500', DV TOOL @ 3491'. M&P 1<sup>ST</sup> STAGE W/ 150sx INTERFILL C FOLLOWED BY 350sx PREMIUM PLUS W/ .3% CFR-3 + .3% D-AIR-1 + .4% LAP-1. DISP W/ FW, BUMP PLUG, DROP BOMP, OPEN DV TOOL, CIRC DV TOOL 4hrs, CIRC 91sx CMT TO PIT. M&P 2<sup>ND</sup> STAGE W/ 800sx INTERFILL C FOLLOWED BY 200sx PREMIUM PLUS W/ 2% CaCl<sub>2</sub>, DISP W/FW, PLUG DOWN 2/1/01, CIRC 91sx CMT TO PIT, BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS, CUT OFF CSG, NUWH & JET CLEAN PITS, REL RIG @ 0600hrs MST 2/2/01. SI WOCU.





