

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: Turner A #44	Facility Type: Injection

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-505311
-----------------------	-----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter N	Section 20	Township 17S	Range 31E	Feet from the 660	North/South Line South	Feet from 2055	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-------------------	------------------------	-------------

Latitude: 32.8146162112349 Longitude -103.893767541586

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release 64 bbls	Volume Recovered 0
Source of Release: Stuffing Box	Date and Hour of Occurrence 12/17/2012 2PM	Date and Hour of Discovery 12/17/2012 2:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD Terry Gregston-BLM	
By Whom? Jose Hernandez	Date and Hour: 12/18/2012 10 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.* DROVE TO LOCATION DOING DAILY ROUTINE NE OF THE TURNER B #137 PROD WELL. WE HAVE TWO TIN HORNS W/ INJECTION VALVE NOTICE WATER COMING OUT FROM AROUND THEM, TURNED INJECTION LINE OFF TO STOP WATER LEAK.

Describe Area Affected and Cleanup Action Taken. There was a 6,951 sq. ft. of pasture area impacted. DFSI was retained to remediate the site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<u>OIL CONSERVATION DIVISION</u>	
Signature: <i>Fred B Wall</i>		Approved by Environmental Specialist:	
Printed Name: Brian Wall			
Title: Construction Foreman II		Approval Date: 8/8/2014	Expiration Date: N/A
E-mail Address: bwall@linenergy.com		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 05/15/20014 Phone: 806-367-0645			

* Attach Additional Sheets If Necessary