

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: H.E. West B #51	Facility Type: Oil Producer	
Surface Owner: Federal	Mineral Owner:	API No.: 30-015-27110

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	10	17S	31E	1337	North	1363	West	Eddy

Latitude: 32.8526523684112 **Longitude:** -103.861754389473

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls	Volume Recovered: 0
Source of Release: Fiberglass pipeline	Date and Hour of Occurrence: 07/23/2014	Date and Hour of Discovery: 07/23/2014 3:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson- BLM / Mike Bratcher NMOCD	
By Whom? Brian Wall	Date and Hour 07/24/2014 0750	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Fiberglass line was exposed due to erosion caused by wind and rain. The line then failed due to the lack of structural support in the area exposed. The line was isolated and the leak stopped. No recovered fluid due to absorption in the sandy location.

Describe Area Affected and Cleanup Action Taken.* : The affected area is 30ft X 30ft.

Directions to Site: From intersection NM 360 and Eddy County 250 north on 250 for 1.2 mi, turn right to dirt road and follow for 1 mi to Y, stay left and follow road for .5 mi turn right and follow road for 2 mi, turn right follow road for .1 mi. left for .1 mi. location is on left side.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Brian Wall	Approved by District Supervisor:		
Title: Construction Foreman II	Approval Date: 8/14/14	Expiration Date: N/A	
E-mail Address: bwall@linenergy.com	Conditions of Approval: Remediation per OCD		Attached <input type="checkbox"/>
Date: 07/24/2014	Phone: 806-367-0645		

* Attach Additional Sheets If Necessary

Rules and Guidelines.
Submit Remediation
Proposal no later than:
9/14/2014