

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/8/2014
NMOCD Artesia

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Stephens & Johnson Operating Co.	Contact William M. Kinkaid
Address P.O. Box 2249, Wichita Falls, TX 76307	Telephone No. (940) 723-2166
Facility Name Mobil 22 Federal #6	Facility Type Well

Surface Owner: Federal	Mineral Owner	Lease No. 30-015-25333
-------------------------------	---------------	-------------------------------

LOCATION OF RELEASE


Unit Letter K	Section 22	Township 26S	Range 29E	Feet from the 2260	North/South Line SOUTH	Feet from the 2310	East/West Line WEST	County EDDY
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude N 32.02664° Longitude W 103.97310 °

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release Unknown	Volume Recovered None
Source of Release: Illegal dumping from a water truck	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 02-18-2014
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Possibly an illegal dump by a water transporter. All of the fluids remained on the well pad.		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez <i>Agent In SEJ</i>		Approved by District Supervisor:	
Title: Senior Project Manager, P.G.		Approval Date: 10/14/2014	Expiration Date: NA
E-mail Address: Ike.Tavarez@tetratech.com		Conditions of Approval:	
Date: 10-8-14 Phone: (432) 682-4559		FINAL	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2262