

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: Bopco, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329
Facility Name: Poker Lake Unit 303 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No.: 30-015-37646	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	4	25S	31E	1264	South	2310	West	Eddy

Latitude: N 32° 9' 19.38" Longitude: W 103° 47' 4.43"

NATURE OF RELEASE

Type of Release: crude oil	Volume of Release: 28 bbl	Volume Recovered: 5 bbl
Source of Release: facility sump	Date and Hour of Occurrence: 7/8/14 time unknown	Date and Hour of Discovery: 7/8/14 @ ~ 3:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD	
By Whom? Tony Savoie	Date and Hour: 7/9/14 @ 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water. ~460 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* A valve was left open on the circulating pump to the sump suction line causing the sump to overflow. Valves were aligned in the correct position.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 1,355 sq. ft. of mostly pasture area. The free standing fluid was recovered, the contaminated soil has been removed and hauled away to a state approved disposal facility and the excavation has been backfilled with clean soil. The impacted area has been cleaned up in accordance to the NMOCD and BLM guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins	Approved by District Supervisor:	
Title: EHS Asst. Remediation Foreman	Approval Date: 10/20/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date: 10-9-14 Phone: (432) 214-3704	FINAL	
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-2374