

October 22, 2014

Oil Conservation Division District 2 – Artesia 811 S. First St. Artesia, NM 88210

Re: Gissler Federal #13H

30-015-38121 Sec. 5, T17S-R30E Eddy County, NM

Mr. Mike Bratcher,

COG Operating LLC would like to submit the enclosed documents for closure of the Gissler Federal #13H release that was reported on the C-141 Initial report dated July 21, 2014.

All work has been completed in accordance with the approved work plan submitted to BLM and OCD along with the excavation stipulation requested by BLM. The impacted area has been excavated and backfilled to its original state. The impacted area will be reseeded in June 2015 with a BLM/LPC Shinnery Site Mixture.

A signed C-141 Final is enclosed for your consideration. Please feel free to contact me with any further questions or concerns at (575) 748-6940.

Sincerely,

Amanda Trujillo

Senior Environmental Scientist

Enclosed: C-141 Initial (Copy)

C-141 Final

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action **OPERATOR** Initial Report Final Repor COG OPERATING LLC Robert McNeill Name of Company Contact Telephone No. 432-230-0077 Address 600 West Illinois Avenue, Midland, TX 79701 Facility Type Battery **Facility Name** Gissler Federal #13H Lease No. (API#) 30-015-38121 Mineral Owner: Federal Surface Owner: Federal LOCATION OF RELEASE East/West Line North/South Line Feet from the County Unit Letter Section Township Range Feet from the 5 17S 30E 1650 South 330 West Eddy Ŧ. Longitude Latitude NATURE OF RELEASE Volume Recovered Volume of Release Type of Release 28 bbls Oil; 12 bbls PW 30 bbls Oil; 15 bbls PW Produced water and Condensate Date and Hour of Discovery Date and Hour of Occurrence Source of Release 07-09-2014 11:00 pm 07-09-2014 11:00 pm Heater treater inside battery If YES, To Whom? Was Immediate Notice Given? Mike Bratcher - NMOCD/Jeffery Robertson - BLM Date and Hour 07-11-2014 05:54 pm By Whom? Amanda Trujillo If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Gasket on the lower manway of the heater treater ruptured causing fluid to spray from the vessel. All free standing fluids picked up and disposed of at an NMOCD approved facility. Describe Area Affected and Cleanup Action Taken.* Main impact area was contained within the bermed area. An area approximately 115' x 25' found directly behind the separating equipment received heavier impact. Adjacent to this area is a 335' x 180' area which is low impact spray area. All free fluids have been recovered. COG will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor. Printed Name: Amanda Trujillo **Expiration Date:** Title: Senior Environmental Coordinator Approval Date: Conditions of Approval: E-mail Address: atrujillo@concho.com Attached

575-748-6940

Phone:

07-21-2014

Date:

^{*} Attach Additional Sheets If Necessary

District 1 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form

Expiration Date:

Attached

Release Notification and Corrective Action OPERATOR ☐ Initial Report Final Report COG OPERATING LLC Name of Company Contact Robert McNeill Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077 Battery Gissler Federal #13H Facility Type Facility Name Surface Owner: Federal Mineral Owner: Federal Lease No. (API#) 30-015-38121 LOCATION OF RELEASE North/South Line Feet from the East/West Line Unit Letter Section Township Range Feet from the County South West Eddy 1650 330 5 17S 30E Latitude Longitude NATURE OF RELEASE Type of Release Volume of Release Volume Recovered 30 bbls Oil; 15 bbls PW Produced water and Condensate 28 bbls Oil; 12 bbls PW Date and Hour of Occurrence Date and Hour of Discovery Source of Release 07-09-2014 11:00 pm 07-09-2014 11:00 pm Heater treater inside battery If YES, To Whom? Was Immediate Notice Given? Mike Bratcher - NMOCD/Jeffery Robertson - BLM Date and Hour 07-11-2014 05:54 pm By Whom? Amanda Trujillo If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Gasket on the lower manway of the heater treater ruptured causing fluid to spray from the vessel. All free standing fluids picked up and disposed of at an NMOCD approved facility. Describe Area Affected and Cleanup Action Taken.* Main impact area was contained within the bermed area. An area approximately 115' x 25' found directly behind the separating equipment received heavier impact. Adjacent to this area is a 335' x 180' area which is low impact spray area. All free fluids have been recovered. COG will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Amanda Trujillo

Approval Date:

Conditions of Approval:

10/22/2014

Title:

E-mail Address:

Senior Environmental Coordinator

atrujillo@concho.com

Phone:

575-748-6940

^{*} Attach Additional Sheets If Necessary