

From: [Blevins, Bradley](#)
To: [Bratcher, Mike, EMNRD](#)
Cc: [Blevins, Bradley](#)
Subject: PLU 78 Release
Date: Monday, August 04, 2014 9:29:46 AM
Attachments: [H402210 EPL.pdf](#)
[doc03472020140722091207.pdf](#)
[30015275360000_57_wf.pdf](#)

Good Morning Mike,

Attached you will find the initial C-141, GPS map, Field Map and Lab data for the cleanup we have going on at the PLU 78. Below is a description of our progress.

SP1-SP2- These sample points are located around the process equipment and had to be hand dug. This area has been dug out to a depth of one foot. As seen in the lab data this area cleans up fairly quickly.

SP3-SP5- These sample points were in the misted area. Area was sprayed with Micro Blaze and soil was blended with ATV and disc rake and reseeded.

SP6-SP7 were located on the well pad. SP6 we meet hand auger refusal past four feet. Four foot sample is 496 chlorides, we excavated one foot from this area. SP7 was excavated to a depth of two feet. With your permission we would like to backfill the release area with clean material and submit final closure documentation. If you have any questions please let me know.

Thanks,
Bradley Blevins