From: Bratcher, Mike, EMNRD
To: "Blevins, Bradley"
Subject: RE: PLU 78 Release

Date: Wednesday, August 06, 2014 9:00:00 AM

Bradley,

Your request to backfill at this site is approved. Federal sites will require BLM approval also. NMOCD tracking number for this release event is: **2RP-2372.** Date of release is 7/4/14.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Mike Bratcher NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108

C: 575-626-0857 F: 575-748-9720

From: Blevins, Bradley [mailto:BBlevins@BassPet.Com]

Sent: Monday, August 04, 2014 9:29 AM

To: Bratcher, Mike, EMNRD Cc: Blevins, Bradley Subject: PLU 78 Release

Good Morning Mike,

Attached you will find the initial C-141, GPS map, Field Map and Lab data for the cleanup we have going on at the PLU 78. Below is a description of our progress.

SP1-SP2- These sample points are located around the process equipment and had to be hand dug. This area has been dug out to a depth of one foot. As seen in the lab data this area cleans up fairly quickly.

SP3-SP5- These sample points were in the misted area. Area was sprayed with Micro Blaze and soil was blended with ATV and disc rake and reseeded.

SP6-SP7 were located on the well pad. SP6 we meet hand auger refusal past four feet. Four foot sample is 496 chlorides, we excavated one foot from this area. SP7 was excavated to a depth of two feet. With your permission we would like to backfill the release area with clean material and submit final closure documentation. If you have any questions please let me know.

Thanks, Bradley Blevins