

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 12/12/14

NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Cypress 34 Federal #1CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-35053 (nearest well)	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	34	23S	29E	460	South	660	East	Eddy

Latitude N 32.25496° Longitude W 103.96596°

#### NATURE OF RELEASE

Type of Release	Oil	Volume of Release	90 bbls	Volume Recovered	80 bbls
Source of Release	Kimray dump valve failed on 3 phase separator causing tanks to spill over	Date and Hour of Occurrence	12/21/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

The failure of a Kimray dump valve on a 3 phase separator caused the tanks to spill 90 bbls of oil onto the ground. 80 bbls of oil were recovered via vacuum truck and the valve was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 30' x 90' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of the NMOCD on 04/01/2014 and approved by Jennifer Van Curen of the BLM via email on 4/22/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Chancey Summers	Approved by Environmental Specialist:		
Title: HES Specialist	Approval Date: 12/19/2014	Expiration Date: NA	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 12-5-14	Phone: (575) 397-8216	FINAL	

\* Attach Additional Sheets If Necessary

2RP-2151