

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 12/18/2014

NMOCD Artesia

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	RJ Unit #136	Facility Type	Flowline

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-34975
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	27	17S	29E					Eddy

Latitude 32 48.210

Longitude 104 03.0928

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 10 B/O, 40 B/PW	Volume Recovered 8 B/O, 15 B/PW
Source of Release Steel flowline	Date and Hour of Occurrence 6-25-2014	Date and Hour of Discovery 6-25-2014 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson-BLM	
By Whom? Michelle Mullins	Date and Hour 06-25-2014 4:23 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

3" steel line corroded due to age, the will be replaced with poly.

Describe Area Affected and Cleanup Action Taken.*

Initially 10 bbls of oil and 40 bbls of produced water were released. We were able to recover 8 bbls of oil and 15 bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Lupe Carrasco		Approved by District Supervisor:	
Title: Environmental Coordinator		Approval Date: 12/26/2014	Expiration Date: NA
E-mail Address: gcarrasco@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date 12-18-2014	Phone: 575-748-6933	FINAL	

* Attach Additional Sheets If Necessary

2RP-2384