

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: PLU-50 Tank Battery and well; 2RP #2251	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-23283

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	4	25S	31E	660	North	1980	East	Eddy

Latitude: N 32.164930° Longitude: W 103.480630°

## NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 10 bbls water	Volume Recovered: none
Source of Release: Water storage tank	Date and Hour of Occurrence: 3/27/14 @ unknown	Date and Hour of Discovery: 3/27/14 @ approx. 2:05 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? The NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 3/27/14 @ 3:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Describe Cause of Problem and Remedial Action Taken.\*

The water production tank overflowed due to a contract trucking company failed to haul water from the facility.

Describe Area Affected and Cleanup Action Taken.\* Nearly the entire area inside the earthen containment was impacted by this release and a prior release on 7/3/13. Reference 2RP-1728. The containment area measures approximately 2,700 sq. ft. The tank battery has been dismantled and a new 0 perm containment has been constructed on the well pad area. The tanks were placed in the new containment and the old tank battery location has been cleaned up. Soil samples were collected, analyzed and based on laboratory analytical results the release area has been excavated and contaminated soil hauled to a state approved disposal facility. The excavation has been backfilled with clean soil. The area has been remediated in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: 

Printed Name: Bradley Blevins

Title: Assistant Remediation Foreman

E-mail Address: bblevins@basspet.com

Date: 2-6-2015 Phone: 432-214-3704

Approved by Environmental Specialist:

Approval Date: 2/6/2015

Expiration Date: NA

Conditions of Approval:

FINAL

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-2251