

Received 3/3/2015

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**
☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-35 The flow line spill was 1,475 ft. southwest of the pad; 2RP #2467	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31167
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 1	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.337484° Longitude: W 103.831995°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 3 bbls oil and 7 bbls water	Volume Recovered: none
Source of Release: 3" poly flow line	Date and Hour of Occurrence: 8/14/14 @ 08:30 am	Date and Hour of Discovery: 8/14/14 @ 08:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	


If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*

The 3" poly line was cut by a road grader operated by MJ Services. The well was shut in and the damaged section of pipe was cut out and replaced.

Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 3,500 sq. ft. of caliche lease road and misted approximately 400 sq. ft. of pasture. The saturated soil was scraped up and stockpiled at the Hudson Federal Battery pending removal. Clean caliche was used to re-cover the exposed line. The release area was excavated and contaminated soil hauled to a state approved disposal facility. Based on laboratory analytical data and NMOCD approval the excavation has been backfilled with clean soil. The area has been remediated in accordance to the NMOCD and BLM guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 3/5/2015	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-18-15 Phone: 432-214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-2467