

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Artec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: OXY Permian	Contact: Christopher Jones
Address: 1502 W Commerce Dr.	Telephone No. 575-499-3337
Facility Name: Conoco State 10 A 1Y Battery	Facility Type:
Surface Owner	Mineral Owner
API No. 30-015-23289	

#### LOCATION OF RELEASE

Unit Letter	Section: 10	Township: 19S	Range: 29E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
-------------	----------------	------------------	---------------	---------------	------------------	---------------	----------------	-----------------

Latitude 32.676970 Longitude -104.065390

#### NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: 3 BBLs Oil 2 BBLs Water	Volume Recovered: 0
Source of Release: High Pressure Vent Line	Date and Hour of Occurrence: 1/10/2015	Date and Hour of Discovery: 1/10/2015 8:45 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
3 inch steel high pressure vent line was compromised causing an approximate 5 bbl impact of produced water and crude oil.		
Describe Area Affected and Cleanup Action Taken.*		
Safety & Environmental Solutions, Inc. was retained by Oxy to fully remediate the above aforementioned site. This site has been remediated according to the remediation/work plan that was approved by the NMOCD representative on February 23, 2015. All remedial activities have been concluded for this site.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <b>Chris Jones</b> <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o=Oxy, email=ckjones@oxy.com, c=US Date: 2015.03.23 14:05:11 -05'00'</small>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name Christopher Jones:	Approved by Environmental Specialist:	
Title: <b>HES SPECIALIST</b>	Approval Date: 3/27/2015	Expiration Date: N/A
E-mail Address: Christopher_jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-23-15 Phone: 575-499-3337	Confirmation samples were	

\* Attach Additional Sheets If Necessary

not supplied to OCD prior  
to backfill as requested.

2RP-2741