

Recieved 3/31/2015

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU #100; 2RP #2817	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-27961	

LOCATION OF RELEASE

Unit Letter O	Section 24	Township 24S	Range 30E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.197390° Longitude: W 103.832060°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 3 bbls crude oil and 5 bbls produced water	Volume Recovered: 1 bbls crude oil and 2 bbl produced water
Source of Release: wellhead fitting	Date and Hour of Occurrence: 2/12/15 @ unknown	Date and Hour of Discovery: 2/12/15 @ approx. 2:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* A 2" pipe fitting failed on the wellhead. The well was shut in and the fitting was replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 2,600 sq. ft. of caliche well pad. All of the free standing fluid was recovered with a vacuum truck. Environmental Plus, Inc. started the remediation activities on 2/13/15. Soil samples were collected, analyzed and based on laboratory analytical results the release area has been excavated and contaminated soil hauled to a state approved disposal facility. With NMOCD approval the excavation was backfilled with clean soil. The area has been remediated in accordance with the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 4/8/2015	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 3-23-15	Phone: 432-214-3704	

* Attach Additional Sheets If Necessary

2RP-2817