

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Allied #002	Facility Type: Producing Oil Well

Surface Owner: State	Mineral Owner: State	API No. 30-015-32497
----------------------	----------------------	----------------------

### LOCATION OF RELEASE

Unit Letter M	Section 22	Township 20S	Range 27E	Feet from the 660'	North/South Line South	Feet from the 660'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude \_\_32.553548\_\_ Longitude \_\_-104.275463\_\_

### NATURE OF RELEASE

Type of Release: Oil(10bbls)	Volume of Release: 10 bbls	Volume Recovered: 0 bbls
Source of Release: Heater Treater	Date and Hour of Occurrence 4-9-14	Date and Hour of Discovery 4-9-14 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Zack Thomas	Date and Hour 4-10-14 7:10 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Heater treater pressured up and blew out the gasket on the fire tube. Well was immediately shut in when discovered.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- Pad surface around the separation equipment. Overspray out into the pasture North of the separation equipment. A small amount of fluid ran off pad 30 feet to the East. All contaminated caliche(on pad) and top soil(east of pad) was dug out and hauled off to Lea Land or R360. (soil samples included) Overspray to the North was sprayed with Micro Blaze (3% cut) and will be monitored to insure product efficiency and if needed will apply additional treatment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<u>OIL CONSERVATION DIVISION</u>	
Signature:		Approved by Environmental Specialist:	
Printed Name: Zack Thomas			
Title: Environmental Rep.		Approval Date: 4/16/15	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com		Conditions of Approval: N/A FINAL	Attached <input type="checkbox"/>
Date: 4-23-14			

\* Attach Additional Sheets If Necessary

2RP-2259