

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Cypress 33 Federal #6H	Facility Type	
Surface Owner	BLM	Mineral Owner	API No. 30-015-41557

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	33	23S	29E					Eddy

Latitude N 32.26685° Longitude W 103.98463°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	5 bbls oil, 195 bbls produced water	Volume Recovered	50 bbls
Source of Release	PRD did not reset on production flow line	Date and Hour of Occurrence	04/28/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, Jennifer Van Curen-BLM		
By Whom?	Kathy Purvis, BBC International Inc.	Date and Hour	04/28/2014 @ 4:36pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A PRD on a production flow line did not reset and caused 195 bbls of produced water and 5 bbls of oil to leak onto the ground. A total 50 bbls of fluids were recovered via vacuum truck and the PRD was repaired/replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 400' x 80' on and off location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/03/2014 and approved by Sol Hughes of the BLM via email on 10/30/2014.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.04.30 12:59:03 -05'00'		OIL CONSERVATION DIVISION			
Signature: Chris Jones		Approved by Environmental Specialist:			
Printed Name: Christopher Jones					
Title: HES Specialist		Approval Date: 5/6/2015		Expiration Date: N/A	
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: Phone: (575) 628-4121		FINAL			

* Attach Additional Sheets If Necessary

2RP-2273