District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Recieved 5/7/2015 NMOCD Artesia

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Santa Fe, NM 8/505											
			Rele	ease Notific	atio	n and Co	rrective A	ction			
						OPERA	ГOR	☐ Init	al Report	Final Report	
Name of Company: Holly Energy Partners, L.P.						Contact: Allison Stockweather, EHS Senior Manager					
Address: 1602 West Main Street, Artesia, NM 88210 Facility Name: Henshaw Station 533						Telephone No.: (575) 746-5475 Facility Type: Truck LACT					
		aw Station 3	33			racinty Typ	e. Truck LACT				
Surface Owner Mineral Owner							API No.				
LOCATION OF RELEASE											
Unit Letter	Section Township Range Feet from the Nort		North	/South Line	Feet from the	East/West Line	County: Eddy County				
pproximately			103.9384 NM.			533 is on the		2 and Square Lal	ce Rd. (Coun	aty Rd. 220);	
Type of Release: Crude Oil Release							Volume of Release: 10 bbls Volume Recovered: 4 bbls				
Source of Release: Broken coupler on pump							Date and Hour of Occurrence: 2/11/2015, 12:30 am Date and Hour of Occurrence: 1:30 am			overy: 2/11/2015,	
Was Immedia	ate Notice	Given?	0.22	No Not Re		If YES, To		Horowitz, NMED,	Spill Hotline	voicemail	
telephone to voicemail). N	NMED at 2 lotification Mike Brat	2:19 am on 2/1 of the inciden	1/2015 (R t was per	eather, gave notic uth Horowitz, NMAC 20.6.2.12 2, of incident deta	03.						
By Whom? Allison Stockweather							Date and Hour: 2/11/2015, 2:19 am				
Was a Watercourse Reached? ☐ Yes ☑ No					If YES, Volume Impacting the Watercourse.						
If a Watercou N/A	irse was Im	pacted, Descr	ibe Fully.*	k							
Describe Cau	se of Probl	em and Reme	dial Action	n Taken.*							
tanks within to contained with liquids satura assessment, r	the tank bath thin an earth ted the soil emediation	ttery overfilled hen berm surr within the rel activities and	I with approunding the ease point waste coo	roximately 10 bar to tank battery. HI . HEP contracted ordination.	rels of EP reco	crude oil and a vered approxi	eleased its liquids mately 4 barrels of	to run, but not pur s onto the ground of the crude oil via a) for project mana	surface. The revacuum truck	elease was	
Describe Are	a Affected	and Cleanup A	Action Tak	en.*							
	R0.73	te Closure Re									
regulations al public health should their co or the environ	I operators or the envi operations I nment. In a	are required tronment. The nave failed to a	o report an acceptance adequately OCD accep	nd/or file certain r se of a C-141 repo investigate and r	elease roort by the emedia	notifications and ne NMOCD m te contaminati	nd perform correct arked as "Final R on that pose a thre	nderstand that pur tive actions for re eport" does not re eat to ground wate responsibility for o	eases which n ieve the opera r, surface water	nay endanger ator of liability er, human health	
Signatura	llist	in Do	chev	eather			OIL CON	SERVATION	DIVISIO	N	

Approved by Environmental Specialist:

Allison Stockweather

Printed Name:

Title: EHS Senior Manager	Approval Date: 5/8/2015	Expiration Date: N/A	
E-mail Address: allison. Stock weather @	Conditions of Approval:	Attached 🛛	
Date: 05/06/15 hollyenergy. com Phone: 575-513-9338	FINA	AL Site Closure Report	

* Attach Additional Sheets If Necessary

2RP-2820