

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 6/24/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Amy C. Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Bass #003W	Facility Type: SWD

Surface Owner: State	Mineral Owner: State	API No. 30-015-10442
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter F	Section 12	Township 19S	Range 28E	Feet from the 2310	North/South Line North	Feet from the 1650	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.676043 Longitude W -104.133229

NATURE OF RELEASE

Type of Release Production Fluids	Volume of Release Unknown	Volume Recovered Unknown
Source of Release	Date and Hour of Occurrence Date and Time Unknown	Date and Hour of Discovery 6/24/14 During final reclamation
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The well was P&A on 2/18/14. A crew started the final reclamation on 6/24/14 after the tanks and equipment had been removed. Heavily impacted soil was discovered around the production tanks and surrounding area.

Describe Area Affected and Cleanup Action Taken.*

The total affected area measured approximately 40,000 sq.ft. The investigation began with test trenches and finally ended up with the advancement of 5 soil bores across the impacted area. The final reclamation was discussed with Mike Bratcher and given the spill report #2RP-2724. Per NMOCD approval, the site was excavated to 6 inches north of the former well marker. South of the former well marker, the site was excavated to 2 ft. bgs, lined with 20 mil plastic and backfilled. The site was contoured to surrounding landscape and re-seeded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth		Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman		Approval Date: 6/26/2015	Expiration Date: N/A
E-mail Address: acruth@basspet.com		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: <u>6-23-15</u> Phone: 432-661-0571			

* Attach Additional Sheets If Necessary

2RP-2724