

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 2/10/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Holly Energy Partners	Contact: Allison Stockweather, EHS Senior Manager
Address: 1602 West Main Street, Artesia, NM 88210	Telephone No.: 575-746-9338
Facility Name: RJU South 4" Pipeline, Crude Oil Gathering	Facility Type: Pipeline

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy County
-------------	---------	----------	-------	---------------	------------------	---------------	----------------	---------------------

Latitude 32.801149 Longitude -104.051554



NATURE OF RELEASE

Type of Release: Crude Oil Release, Pipeline	Volume of Release: 28 bbls	Volume Recovered: 15 bbls
Source of Release: Hole in pipeline	Date and Hour of Occurrence: 03/09/14, 11:20 AM	Date and Hour of Discovery: Updated information provided to EHS on 03/10/14, 11:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required HEP EHS telephone notification to NMED was made within 24 hours to Ruth Horowitz who submitted the notification to OCD.	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
Please see attached CRA 2RP-2367 Site Closure Report.

Describe Area Affected and Cleanup Action Taken.*
Please see attached CRA 2RP-2367 Site Closure Report

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Allison Stockweather	Approved by Environmental Specialist: 		
Title: EHS Senior Manager	Approval Date: 7/7/2015	Expiration Date: N/A	
E-mail Address: Allison.Stockweather@hollyenergy.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 02/03/15	Phone: 575-746-5475		

* Attach Additional Sheets If Necessary

2RP-2367