

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Received 7/7/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Linn Operating Inc.	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM 88240	Telephone No.	575-738-1739
Facility Name	Lea D #23	Facility Type	Oil Producer
Surface Owner	Federal	Mineral Owner	API No. 30-015-29703

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	26	17S	31E	1322	North	1322	West	Eddy

Latitude 32.8092232 Longitude -103.8445892 NAD83

NATURE OF RELEASE



Type of Release	Oil / Produced Water	Volume of Release	3 gal / 3 gal	Volume Recovered	0 / 0
Source of Release	flow line fuse	Date and Hour of Occurrence	07/03/2015	Date and Hour of Discovery	07/03/2015 1:13pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* As I was driving to the Lea D #23 just north east of Lea D #7 injection well I saw the flow line from well #23 spraying fluid into the pasture. I drove to the Lea D #23 and shut the well in to stop it from making a bigger mess. The fluid was coming out from an old fuse that gave out. I called the roustabout gang to come and refuse the flow line and also called a backhoe to come and clean up the impacted area.

Describe Area Affected and Cleanup Action Taken.* The impacted area was about a 10ft by 10ft area

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: E.L. Gonzales	Approved by Environmental Specialist: 		
Title: Production Supervisor	Approval Date: 7/10/2015	Expiration Date: N/A	
E-mail Address: elgonzaes@linenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 07/07/2015 Phone: 505-504-8002	Remediation Per OCD Rules and Guidelines		

* Attach Additional Sheets If Necessary

Submit Remediation Proposal No
Later Than 8/10/2015

2RP-3095