

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003
 Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company : LIME ROCK RESOURCES II-A, LP	Contact : Mike Barrett
Address : 1111 Bagby Street Suite 4600, Houston ,TX 77002	Telephone No. : 575-623-8424
Facility Name: Logan 35 Water Transfer Line	Facility Type: Transfer Line

Surface Owner : BLM	Mineral Owner: BLM	API:30-015-30439
---------------------	--------------------	------------------

LOCATION OF RELEASE

Unit Letter N	Section 35	Township 17S	Range 27E	Feet from the North/South Line	Feet from the East/West Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------------------	---------------------------------	----------------

Latitude 32.78584 N Longitude -104.25050 W

NATURE OF RELEASE


Type of Release : Mix Fluids	Volume of Release : 350 bbls PW 5 bbls Oil	Volume Recovered: 300 bbls PW 1 bbl Oil
Source of Release : Downed Power Line	Date and Hour of Occurrence: 6/25/2015 3:30 pm	Date and Hour of Discovery: 6/25/2015 @ 3:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM/Jeffery Robertson & OCD/Mike Bratcher - voicemail	
By Whom? Sheldon Hitchcock with Talon/LPE	Date and Hour :6/25/2015 @ 4:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A downed power line ignited causing a fire which melted the flow lines. The facility and wells were shut in. The BLM fire department responded to extinguish the fire. Once the fire was out the flowlines were cut and capped with valves and later repaired and put back into service. Vacuum trucks were immediately called to the site and recovered 300 barrels of produced water and 1 barrel of oil. Talon/LPE was contacted for the emergency response.

Describe Area Affected and Cleanup Action Taken.* Talon mobilized personnel and equipment for emergency response, site assessment, soil sampling and generation of the work plan. Upon approval of the work plan the remediation was conducted per the approved work plan. The excavation was backfilled, contoured to match the surrounding terrain and seeded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor: 	
Title: Production Supervisor	Approval Date: 7/24/2015	Expiration Date: NA
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 7/21/2015 Phone: 575-623-8424		

* Attach Additional Sheets If Necessary

2RP-3084