

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: EOG Resources	Contact: Zane Kurtz
Address: 5909 Champions Drive, Midland, Texas 79706	Telephone No.: (432)686-3667
Facility Name: Elk Wallow 11 #8	Facility Type: Well site and separator

Surface Owner: New Mexico State Land Office	Mineral Owner: New Mexico State Land Office	API No.: 300153972300
---	---	-----------------------

### LOCATION OF RELEASE

Unit Letter B	Section 11	Township: 25S	Range 29E	Feet from the 160	North/South Line North	Feet from the 2655	East/West Line East	County: Eddy
------------------	---------------	------------------	--------------	----------------------	---------------------------	-----------------------	------------------------	-----------------

Latitude 32.1515 Longitude -103.9551

### NATURE OF RELEASE

Type of Release: Blowout on bottom of motor valve	Volume of Release: 25 bbls	Volume Recovered: 15 bbls
Source of Release: Motor valve.	Date and Hour of Occurrence: 3/2/15, Time Unknown	Date and Hour of Discovery: 3/2/15, 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

The bottom motor valve on the separator broke allowing gas and produced water to be released. A vacuum truck was brought to the site and as much fluid as possible was recovered. Some spray from the release went off-site and onto the adjacent pasture. Impacted soils were excavated and disposed of.

Describe Area Affected and Cleanup Action Taken.\*

Impacted soil was excavated and properly disposed of. The excavated area will be backfilled with clean soil and revegetated pending approval from NMOCD. See attached closure report

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Zane Kurtz	Approved by Environmental Specialist:		
Title: Sr. Environmental Rep, EOG	Approval Date:	Expiration Date:	
E-mail Address: Zane.Kurtz@eogresources.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8-4-15	Phone: 432 925 2023		

\* Attach Additional Sheets If Necessary