

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Cimarex Energy	Contact	Gloria Garza
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-234-3204
Facility Name	Bonnie 35 Federal Com	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No.	30-015-42956
---------------	---------	---------------	--	-----------	--------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	35	25S	26E	200	PSL	970	FEL	Eddy

Latitude 32.0795801765834 Longitude -104.258295270376

#### NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15 bbls	Volume Recovered	5 bbls
Source of Release	Water transfer line	Date and Hour of Occurrence	6-18-15	Date and Hour of Discovery	6-18-15 7:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Jeff Robertson		
By Whom?	Gloria Garza	Date and Hour	6/19/15 9:26 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			


If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A hammer union on the water transfer line came loose due to vibration from pressure.

Describe Area Affected and Cleanup Action Taken.\*

An area of 2,842 sq. ft. was impacted. Diversified Environmental Services attained clean samples at 1' bgs at three sample points. The entire area was excavated to 1'bgs. Fresh caliche was brought in for backfill. All contaminated soil was hauled to an approved NM state disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Gloria Garza	Approved by District Supervisor:	
Title: ESH Tech	Approval Date: 9/21/2015	Expiration Date: N/A
E-mail Address: ggarza@cimarex.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 9/15/2015	Phone: 432-234-3204	

\* Attach Additional Sheets If Necessary

2RP-3063