

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 9/21/2015  
NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB1432249850

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Lost Tank 4 Federal #19 Battery	Facility Type	Well/Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-37896

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	4	22S	31E					Eddy County, NM

Latitude N 32.41907° Longitude W 103.78400°

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	10 bbls oil, 30 bbls produced water	Volume Recovered	0 bbls
Source of Release	Corrosion of a 2" steel production flow line	Date and Hour of Occurrence	11/03/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD, Sol Hughes- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	11/04/2014 @ 4:29 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Corrosion of a 2" steel production flow line caused 10 bbls of oil and 30 bbls of produced water to leak onto the ground. No fluids were recovered and the line was repaired/replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 90' x 60' on and off location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 05/29/2015 and approved by Jeffrey Robertson of the BLM via email on 06/25/2015 as well as Shelly Tucker of the BLM via email on 07/14/2015.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Chancey Summers		Approved by Environmental Specialist: <i>MBratcher</i>			
Title: HES Lead		Approval Date: 9/22/14		Expiration Date: N/A	
E-mail Address: <u>Chancey.Summers@oxy.com</u>		Conditions of Approval: N/A		Attached <input type="checkbox"/>	
Date: <u>9-11-15</u> Phone: (432) 685-5824		FINAL			

\* Attach Additional Sheets If Necessary

2RP-2602