

**From:** [Pam Inskeep](#)  
**To:** [Patterson, Heather, EMNRD](#)  
**Subject:** RE: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200  
**Date:** Tuesday, September 22, 2015 12:06:59 PM  
**Attachments:** Pardue D Sample Map.pdf

---

Hi, Heather.

As requested, attached is a site map detailing the sample points. Please advise, should you need anything further to approve for excavation and backfill..

Thanks,

Pam

---

**From:** Pam Inskeep  
**Sent:** Wednesday, September 16, 2015 9:25 AM  
**To:** 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>  
**Subject:** RE: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

We will get one to you.

Thanks,

Pam

---

**From:** Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]  
**Sent:** Wednesday, September 16, 2015 9:09 AM  
**To:** Pam Inskeep <[Pinskeep@btaoil.com](mailto:Pinskeep@btaoil.com)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Subject:** RE: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

**RE: BTA \* Pardue D, 8808 JV-P #1 \* 2RP-3200**

Ms. Inskeep,

I cannot approve your backfill request without a little more information. I will need a site map showing each one of your data points on it, and a description of the work done (depth of excavation).

Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Pam Inskeep [<mailto:Pinskeep@btaoil.com>]  
**Sent:** Monday, September 14, 2015 9:17 AM  
**To:** Patterson, Heather, EMNRD  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

Good morning.

Attached, please find copies of the sample analyses performed at this site on 9/10/2015.

Please review and advise as to approval for excavation and backfill.

Thanks,

Pam

---

**From:** Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]  
**Sent:** Friday, August 21, 2015 10:17 AM  
**To:** Pam Inskeep <[Pinskeep@btaoil.com](mailto:Pinskeep@btaoil.com)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Subject:** RE: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325

**BTA \* Pardue D 8808 JV-P #1 \* 30-015-26274 \* 2RP-3200**

Ms. Inskeep,

The OCD has received and processed your initial release notification for the above listed site. In the C-141 it is stated that BTA will excavate the contaminated soil and replace with clean soil. The OCD will require a full delineation at this site to be submitted in a work plan to the district 2 office before this site is excavated and backfilled. The OCD tracking number for this incident is 2RP-3200.

If you have any questions or concerns, please don't hesitate to call.

Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Pam Inskeep [<mailto:Pinskeep@btaoil.com>]  
**Sent:** Thursday, August 13, 2015 4:13 PM  
**To:** Patterson, Heather, EMNRD  
**Subject:** C141 - BTA 8808 JV-P Pardue D #1 30-015-26325

Good afternoon, Heather.

Attached is a C-141 initial report re our 8808 JV-P Pardue D #1.

Please give a shout with any questions.

Thanks,

Pam

Pam Inskeep  
Regulatory Administrator  
BTA Oil Producers LLC  
104 S. Pecos  
Midland, TX 79701  
432-682-3753  
[pinskeep@btaoil.com](mailto:pinskeep@btaoil.com)