

From: Patterson, Heather, EMNRD
To: ["Pam Inskeep"](#)
Subject: RE: REPLY: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200
Date: Wednesday, September 23, 2015 12:41:00 PM

Thank you Pam,

Your backfill request is approved.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Pam Inskeep [mailto:Pinskeep@btaoil.com]
Sent: Wednesday, September 23, 2015 12:39 PM
To: Patterson, Heather, EMNRD
Subject: REPLY: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

Sorry, Heather. I neglected to provide you that info. The background sample was from the surface. All of the other sampling points were taken at 1-1/2' deep.

Thanks,

Pam

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]
Sent: Wednesday, September 23, 2015 1:34 PM
To: Pam Inskeep <Pinskeep@btaoil.com>
Subject: RE: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

Pam,

Are these samples from the surface or from the bottom of your excavation? If they are from the excavation, how deep is that excavation?

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101

Cell (575)703-0228

From: Pam Inskeep [<mailto:Pinskeep@btaoil.com>]
Sent: Tuesday, September 22, 2015 12:06 PM
To: Patterson, Heather, EMNRD
Subject: RE: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

Hi, Heather.

As requested, attached is a site map detailing the sample points. Please advise, should you need anything further to approve for excavation and backfill..

Thanks,

Pam

From: Pam Inskeep
Sent: Wednesday, September 16, 2015 9:25 AM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>
Subject: RE: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

We will get one to you.

Thanks,

Pam

From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]
Sent: Wednesday, September 16, 2015 9:09 AM
To: Pam Inskeep <Pinskeep@btaoil.com>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: RE: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

RE: BTA * Pardue D, 8808 JV-P #1 * 2RP-3200

Ms. Inskeep,

I cannot approve your backfill request without a little more information. I will need a site map showing each one of your data points on it, and a description of the work done (depth of excavation).

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II

Office (575)748-1283 ext.101
Cell (575)703-0228

From: Pam Inskeep [<mailto:Pinskeep@btaoil.com>]
Sent: Monday, September 14, 2015 9:17 AM
To: Patterson, Heather, EMNRD
Cc: Bratcher, Mike, EMNRD
Subject: FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200

Good morning.

Attached, please find copies of the sample analyses performed at this site on 9/10/2015.

Please review and advise as to approval for excavation and backfill.

Thanks,

Pam

From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]
Sent: Friday, August 21, 2015 10:17 AM
To: Pam Inskeep <Pinskeep@btaoil.com>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: RE: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325

BTA * Pardue D 8808 JV-P #1 * 30-015-26274 * 2RP-3200

Ms. Inskeep,

The OCD has received and processed your initial release notification for the above listed site. In the C-141 it is stated that BTA will excavate the contaminated soil and replace with clean soil. The OCD will require a full delineation at this site to be submitted in a work plan to the district 2 office before this site is excavated and backfilled. The OCD tracking number for this incident is 2RP-3200.

If you have any questions or concerns, please don't hesitate to call.

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Pam Inskeep [<mailto:Pinskeep@btaoil.com>]
Sent: Thursday, August 13, 2015 4:13 PM
To: Patterson, Heather, EMNRD
Subject: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325

Good afternoon, Heather.

Attached is a C-141 initial report re our 8808 JV-P Pardue D #1.

Please give a shout with any questions.

Thanks,

Pam

Pam Inskeep
Regulatory Administrator
BTA Oil Producers LLC
104 S. Pecos
Midland, TX 79701
432-682-3753
pinskeep@btaoil.com