

REC'D VIA EMAIL 11/11/09

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company COG OPERATING LLC	Contact Kanicia Carrillo
Address 550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No. 432-685-4332
Facility Name - Skelly Unit 942	Facility Type- Battery

Surface Owner Federal	Mineral Owner	Lease No. 30-015-34645
-----------------------	---------------	------------------------

LOCATION OF RELEASE

Unit Letter B	Section 22	Township 17S	Range 31E	Feet from the 1210	North/South Line North	Feet from the 2195	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N32'.49.477' Longitude W03'.51.336

NATURE OF RELEASE

Type of Release-Oil	Volume of Release-20bbls	Volume Recovered- 10bbls
Source of Release- 500bbl production tank	Date and Hour of Occurrence- 11/03/09 Approx 3:12pm	Date and Hour of Discovery 11/03/09 Approx 3:12pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

We out ran the capacity of the equalizer line on the 500bbl tank while circulating non-sellable oil.

Describe Area Affected and Cleanup Action Taken.*

Spill contained within dike. Removed saturated soil. Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kanicia Carrillo	Approved by District Supervisor: 	
Title: Regulatory Analyst	Approval Date: 10/5/05	Expiration Date: N/A
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/11/09 Phone: 432-685-4332		

* Attach Additional Sheets If Necessary

Incident closed per closure document sent
5/12/2010

2RD-3311