

Rec'd 12/29/2014

State of New Mexico **NMOCD Dist 2**  
**Energy Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 South St. Francis Dr.**  
**Santa Fe, NM 87505**

**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
**District II**  
 1301 W. Grand Avenue, Artesia, NM 88210  
**District III**  
 1000 Rio Brazos Road, Aztec, NM 87410  
**District IV**  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

**Form C-141**  
 Revised October 10, 2003

Submit 2 Copies to appropriate  
 District Office in accordance  
 with Rule 116 on back  
 side of form

**Release Notification and Corrective Action****OPERATOR**
☐ Initial Report ☒ Final Report

Name of Company <b>COG Operating LLC</b>	Contact <b>Robert McNeil</b>
Address <b>600 West Illinois Avenue, Midland, Texas 79701</b>	Telephone No. <b>(432) 230-0077</b>
Facility Name <b>GJ West Coop Unit #074</b>	Facility Type <b>Well</b>
Surface Owner: <b>State</b>	Mineral Owner
	Lease No. <b>30-015-25492</b> <b>30-015-03163</b>

**LOCATION OF RELEASE**

Unit Letter <b>H</b>	Section <b>28</b>	Township <b>17S</b>	Range <b>29E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude N 32.81225° Longitude W 104.0774°

**NATURE OF RELEASE**

Type of Release: <b>Produced water w/skim oil</b>	Volume of Release <b>15 bbls</b>	Volume Recovered <b>12 bbls</b>
Source of Release <b>casing</b>	Date and Hour of Occurrence <b>06-06-2012</b>	Date and Hour of Discovery <b>06-06-2012 8:30a.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*

N/A


Describe Cause of Problem and Remedial Action Taken.\*

The well developed a hole in the casing, allowing water flow from injection wells. A clamp was placed on the casing and the well was turned in for repair.

Describe Area Affected and Cleanup Action Taken.\*

Tetra Tech inspected site and collected samples to define spills extent. Selected areas with soils that exceeded RRAL were removed and hauled away for proper disposal if accessible. Liners were installed according to the work plan. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Ike Tavarez (Agent for COG)</b>	Approved by District Supervisor: <b>MBratcher</b>	
Title: <b>Project Manager, P.G.</b>	Approval Date: <b>11/4/15</b>	Expiration Date:
E-mail Address: <b>ike.tavarez@tetrattech.com</b>	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: <b>12/11/14</b> Phone: <b>(432) 687-8110</b>		

\* Attach Additional Sheets If Necessary

2RP-1182