

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 12/7/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Nash Draw 8 SWD #1 (2RP-2081)	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41351

LOCATION OF RELEASE


Unit Letter L	Section 8	Township 24S	Range 30E	Feet from the 2075	North/South Line South	Feet from the 630	East/West Line West	County: Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	--------------

Latitude N 32.231646 Longitude W 103.910656

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 10 bbls crude oil and 4,357 bbls produced water	Volume Recovered: 7 bbls crude oil and 4,207 bbls produced water.
Source of Release: Gun-barrel over flow	Date and Hour of Occurrence 11/22/13 at 3:00 a.m.	Date and Hour of Discovery: 11/22/13 at 3:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency number 104 and the BLM	
By Whom? Tony Savoie	Date and Hour 11/22/13 at 8:16 a.m., BLM 11/22/13 at 8:19 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Water was being transferred into the gun-barrels and the facility storage tanks to supply water to the Aquilla rig #8, a valve was discovered closed on the transfer line to the storage tanks causing the gun-barrels to overflow inside the impervious containment. The containment overflowed into the adjoining impervious containment around the skim tank and onto the ground. The valve alignment was corrected and vacuum trucks started recovering the spilled produce water.		
Describe Area Affected and Cleanup Action Taken.* <i>Basin Environmental began the spill remediation efforts for the PW spill on 12/3/13 and was completed on 2/7/14. During this time frame approximately 8,020 cubic yards of contaminated soil was removed from site and transported to an approved NMOCD disposal site. Please reference the Remediation Summary & Risk-Based Closure Request dated December 2015.</i>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:	
Printed Name: Tony Savoie	Approval Date: 12/7/2015	Expiration Date: N/A
Title: Waste Management and Remediation Specialist	Conditions of Approval:	
E-mail Address: tasavoie@basspet.com	Attached <input type="checkbox"/>	
Date: 12/7/15 Phone: 432-556-8730	FINAL	

* Attach Additional Sheets If Necessary

2RP-2081