

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 12/4/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	Contact Amber Griffin
Address 104 S. 4 th Street	Telephone No. 575-748-1471
Facility Name Harkey 35 State #1	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-25812
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter J	Section 35	Township 24S	Range 27E	Feet from the 2180	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.17225 Longitude 104.15877

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 15 B/PW
Source of Release Production Tank	Date and Hour of Occurrence 4/21/2015; AM	Date and Hour of Discovery 4/21/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 4/22/2015; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The water pump failed and did not start, causing the produced water tank to overflow. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 15' X 15' inside and outside of the unlined berm. The water pump was started and vacuum trucks were called to recover the spill. Impacted soils will be excavated and hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: 50-99' (approximately 60', Section 35, T24S-R27E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Yates Petroleum requests closure as all work was completed per NMOCD approved work plan.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Amber Griffin</u>	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Amber Griffin	Approved by Environmental Specialist:		
Title: NM Environmental Regulatory Agent	Approval Date: 12/8/2015	Expiration Date: N/A	
E-mail Address: agriffin@yatespetroleum.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: December 4, 2015	Phone: 575-748-4111	2RP-2997	FINAL

* Attach Additional Sheets If Necessary