

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 11/2/2015  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: San Lorenzo SWD #001	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-23067
----------------------	----------------	----------------------

### LOCATION OF RELEASE

Unit Letter H	Section 34	Township 25S	Range 28E	Feet from the 2450'	North/South Line North	Feet from the 1140'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.08707 Longitude -104.06766

### NATURE OF RELEASE

Type of Release: Produced water/Oil	Volume of Release: estimated 1726 bbls total fluid (1473 bbls PW & 253 bbls Oil)	Volume Recovered: Oil (253 bbls) PW/rain water (267 bbls)
Source of Release: Damaged 4" SDR7 poly line	Date and Hour of Occurrence 9-26-14	Date and Hour of Discovery 9-28-14 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Zack Thomas	Date and Hour 9-28-14 6:50 pm	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 1726 bbls	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

SWD line ran alongside west side highway 285 from the San Lorenzo SWD to the Delaware Ranch SWD was damaged in the draw between mile marker 6 and mile marker 7 under bridge while draw was flowing.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- The draw was affected from the bridge at highway 285 to approximately six thousand feet East down the draw. Vacuum trucks immediately recovered 253 BO & 267 BW from the flowing draw. Skimmers were also used to recover remaining visible oil on pool areas of the draw. MOC placed oil absorbing booms and pads on the wet and dry portions of the draw and used hand tools to remove impacted vegetation and soils. After water, sediment, and soil samples confirmed that there were no areas above the RRAL, MOC proposed spraying remaining impacted areas with Micro-blaze. OCD and SLO approved this closure procedure and the Micro-blaze treatment was performed on October 29<sup>th</sup>, 2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	
Title: Environmental Rep.	Approval Date: 12/14/2015	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-30-15	Phone: 575-602-2188	FINAL

\* Attach Additional Sheets If Necessary

2RP-2532