

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB1502141294

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Marauder Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-015-38244
------------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	31	19S	31E	330	North	660	West	Eddy

Latitude 32.6231450328974 Longitude -103.914919290024

**NATURE OF RELEASE**


Type of Release: Oil and Produced Water	Volume of Release: 15 bbls Oil; 10 bbls PW	Volume Recovered: 0 bbls Oil; 0 bbls PW
Source of Release: Flare	Date and Hour of Occurrence: 1/1/2015 12:00 am	Date and Hour of Discovery: 1/1/2015 12:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
 This release was caused by a problem at the battery that lead to fluid coming out the flare. Soapy water and Microblaze was applied to the impacted pasture and vegetation.

Describe Area Affected and Cleanup Action Taken.\*  
 The impacted area is located adjacent to battery and is approximately 300' x 600' in size. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr	Approved by Environmental Specialist: <i>MBratcher</i>	
Title: Senior Environmental Coordinator	Approval Date: 12/14/2015	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: November 10, 2015	Phone: 432-661-6601	<b>FINAL</b>

\* Attach Additional Sheets If Necessary