

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 12/11/2015
NMOCD District 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1504838579

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Dirty Dozen State Com #3H	Facility Type: Wellhead

Surface Owner: State	Mineral Owner:	API No. 30-015-38225
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter I	Section 36	Township 19S	Range 31E	Feet from the 1810	North/South Line South	Feet from the 720	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.6146940334203 Longitude -103.816411683419

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 25 bbls Oil ; 6 bbls PW	Volume Recovered: 20 bbls Oil ; 5 bbls PW
Source of Release: Wellhead	Date and Hour of Occurrence: 1/29/2015 7:00 am	Date and Hour of Discovery: 1/29/2015 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 5:37 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release was caused when the wellhead pressured up and the packing failed to hold. Vacuum trucks were dispatched to pick up all standing fluids.

Describe Area Affected and Cleanup Action Taken.*

This release was contained to the pad area. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Robert Grubbs Jr	Approved by Environmental Specialist: <i>MBratcher</i>		
Title: Senior Environmental Coordinator	Approval Date: 12/14/2015	Expiration Date: N/A	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: October 12, 2015 Phone: 432-661-6601	FINAL		

* Attach Additional Sheets If Necessary

2RP-2815