Rebecca,

The BLM accepts/approves this work plan.

Please notify me of the analytical results from the sidewalls and final excavation footages (LxWxD).

NOTE:

The BLM approval/acceptance does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

If you have any questions or concerns, please do not hesitate to contact me.

On Friday, September 4, 2015, Rebecca Pons <<u>office2@sesi-nm.com</u>> wrote:

Good morning,

Heather; thank you for pointing out the additional 4<sup>th</sup> page. I have removed this page. The correct verbiage is now in place on the correct placement of the 4<sup>th</sup> page, in that we are backfilling the current excavation to the depth of 18", lining, backfilling with a layer of topsoil, completing with like surface material and restoring surface to grade.

Per your request: I will notify you of field sample results for the sidewalls of the East and South Walls respectively. If for some reason, I am >1000 mg/kg on Cl constituents, I will notify each of you for an exception.

Thank You

Rebecca Pons

Safety & Environmental Solutions, Inc.

703 East Clinton Street

Hobbs, NM 88240

Office: (575) 397-0510

Sincerely,

---

Shelly J. Tucker Environmental Protection Specialist Bureau of Land Management

620 E. Greene St Carlsbad, NM 88220

575.234.5905 - Direct 575.361.0084 - Cellular

stucker@blm.gov

Sent from Gmail Mobile