

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nAB1521756095

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: Memorial Production Operating LLC	Contact: Heather Dolphin	
Address: 500 Dallas Street Houston TX 77002	Telephone No.: 832-797-1334	
Facility Name: KLM Battery	Facility Type: Production	
Surface Owner:	Mineral Owner:	API No.: 30-015-04411

LOCATION OF RELEASE

Unit Letter	Section 31	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: 32.791267 Longitude: -104.012383

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 7 bbls oil 23 bbls PW	Volume Recovered: 30 bbls
Source of Release: Battery	Date and Hour of Occurrence: 8/2/15	Date and Hour of Discovery: 8/2/15 10am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM & Heather Patterson, NMOCD	
By Whom? Heather Dolphin Sr. Regulatory Specialist	Date and Hour 8/2/15 4:17 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a	
If a Watercourse was Impacted, Describe Fully.*: n/a		
Describe Cause of Problem and Remedial Action Taken.*: A valve upstream from the circulating pump washed out and wouldn't hold fluid back. The spill filled up the berm around the circ. pump and overflowed it.		
Describe Area Affected and Cleanup Action Taken.*: Impacted area around transfer pump inside containment; containment overflowed and fluid ran down lease road approx. 220 ft, through the pasture approx 100 ft, and down the bar ditch of the county road approx. 80 ft. Vacuumed up all free standing fluid. Site was excavated and soils were treated per OCD and BLM requirements in approved CAP.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tim McMinn	Approved by District Supervisor: MBratcher	
Title: Etech Environmental	Approval Date: 1/12/2016	Expiration Date: N/A
E-mail Address: tim@etechenv.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 1/11/16	Phone: 432-967-9062	FINAL REPORT

* Attach Additional Sheets If Necessary

2RP-3188