

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 1/11/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730	
Facility Name: Poker Lake Unit 213 SWD	Facility Type: Salt Water Disposal Tank Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-33859

LOCATION OF RELEASE

Unit Letter P	Section 18	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.212384

Longitude: W 103.914812

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release: 550-700 Bbls	Volume Recovered : 260 Bbls
Source of Release : Tank Battery	Date and Hour of Occurrence: N/A	Date and Hour of Discovery: 11/26/05 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Gary Fletcher	Date and Hour 11/26/05 10:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Pump failure at Tank Battery. Improve system by installing additional storage and possibly high tank level alarms.

Describe Area Affected and Cleanup Action Taken.*

Very Sandy and poor vegetation.

The spill area was sampled by Basin Environmental on 2/9/15. A meeting was held with the Artesia NMOCD on 3/4/15 to discuss and review needed remediation activity. Reference the attached Site Closure Request dated January 2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Tony Savoie		Approved by Environmental Specialist:	
Title: Waste Mgmt. and Remediation Specialist		Approval Date: 1/13/2016	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: Phone: 432-556-8730		FINAL	
		Attached <input checked="" type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3490