

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	PPC OPERATING COMPANY LLC	Contact	JANA SPRABERRY
Address	1500 INDUSTRIAL BLVD, STE 304; ABILENE TX 79602	Telephone No.	325-267-6046
Facility Name	RUSTLER BLUFF #001	Facility Type	TANK BATTERY

Surface Owner	STATE OF NEW MEXICO	Mineral Owner	STATE OF NEW MEXICO	API No.	30-015-34839
---------------	---------------------	---------------	---------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	06	25S	29E	1980	SOUTH	1680	EAST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	OIL & PRODUCED WATER	Volume of Release	256 OIL/193 WTR	Volume Recovered	NONE
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	9/23/14 - NOC
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	TOMAS OBERDING (HOBBS); MIKE BRATCHER (ARTESIA)		
By Whom?	JANA SPRABERRY	Date and Hour	9/24/14; 8:00 AM		
Was a Watercourse Reached?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	256 OIL / 193 WATER		

If a Watercourse was Impacted, Describe Fully.*

SWIFT WATER FLOODING OCCURRED ALONG PECOS RIVER WASHING AWAY ONE 500 BBLs TANK BATTERY CONTAINING 256 BBLs OIL.


Describe Cause of Problem and Remedial Action Taken.*

SWIFT WATER FLOODING OF PECOS RIVER WASHED AWAY AN OIL TANK AT THE BATTERY; NM OCD WAS NOTIFIED. THE TANK WAS LOCATED BY THE NM OCD DOWNSTREAM OF THE BATTERY ON THE OPPOSITE SIDE OF RIVER. FURTHER ACTION WILL BE TAKEN AS SOON AREA DRIES OUT.

Describe Area Affected and Cleanup Action Taken.*

THE TANK WAS RECOVERED BY THE RANCHER WHEN CONDITIONS WERE DRY ENOUGH. WE CONTRACTED GREG SWINDLE WITH DBI ENVIRONMENTAL TO SAMPLE AND TEST THE BATTERY PAD WHERE THE TANK WAS WASHED AWAY FROM AND THE SITE WHERE THE TANK WAS FOUND AFTER THE FLOOD. THE LAB RESULTS INDICATE THERE ARE NO CONTAMINANTS PRESENT. A COPY OF THE LAB ANALYSES ARE ATTACHED.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: JANA SPRABERRY	Approved by Environmental Specialist:		
Title: OFFICE ADMINISTRATOR	Approval Date: 1/20/2016	Expiration Date: N/A	
E-mail Address: JSRABERRY@PLANTATIONPETRO.COM	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 01-11-2016	Phone: 325-267-6046	FINAL	

* Attach Additional Sheets If Necessary

2RP-2518