Received 1/14/2016 NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Final Report

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Initial Report** 

**OPERATOR** 

		OG Operati	_			Contact: Robert McNeill					
Address: 60	0 West Illi	inois Avenu	d TX 79701		Telephone No. 432-230-0077						
Facility Nar	ne: BRUT	OM #002H		Facility Type: 30-015-40823							
Surface Ow	nom Fodom	o1	Mineral C	)	ADI No. 20 015 40022						
Surface Ow	ner: reder	aı	Milleral C	Jwner:	API No. 30-015-40823						
				LOCA	ATIO	N OF REI	LEASE				
Unit Letter	Section	Feet from the		/South Line	Feet from the	East/	West Line	County			
О	12	26S	28E	370'		South	2260'		East	Eddy	
				Latitude 32 (	150865	2 I ongitude	-104.0394058				
						OF RELI					
Type of Rele	ase.			1 17 1	CKE	Volume of			Volume R	ecovered:	
Oil	150.			85 bbls Oil 59 bbls Oil							
Source of Release:						Date and H	Date and Hour of Occurrence: Date and Hour of Discovery:				
Steel Flowline						10/2/2015 7:00 pm 10/2/2015 7:00 pm					
							If YES, To Whom?				
☐ Yes ☐ No ☐ Not Required ☐ Mike Bratcher – NMOCD											
By Whom?	By Whom? Lupe Carrasco						Date and Hour: Sat 10/3/2015 8:40 PM				
Was a Water				If YES, Volume Impacting the Watercourse.							
☐ Yes ⊠ No											
If a Watercou	rse was Im	pacted. Descr	ibe Fully.*	k							
		_	-								
Describe Cause of Problem and Remedial Action Taken.*											
This release was caused by a corroded steel flowline. A vacuum truck was dispatched to recover all standing fluid.											
Describe Are	n Affactad	and Cleanup	Action Tal	ran *							
Describe Are	a Affecteu a	and Cleanup 7	ACTION TAN	ten.							
The corroded	The corroded flow line broke on the edge of the containment. Impact did occur to the nearby pasture. This release was addressed per the approved										
		guidance of N					J P			r	
-		_									
										ant to NMOCD rules and	
										ases which may endanger	
	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
		ws and/or regu		nance of a C-141	report d	ioes not renev	e the operator of i	espons	ibility for co	impliance with any other	
icuciai, state,	or rocar ray	ws and/or regu	nanons.		1		OIL COM	CEDI	ATION	DIVISION	
		1 -					OIL CON	OLK V	ALIUN	DI VIDIOIN	
Cianatura	d	manda	T. La	ws							
Signature:				Approved by	Environmental S <sub>1</sub>	necialis	t:				
Printed Name	· Amanda										
1 mica mani	. minanda	1101110			+						
Title: Senior	Environme	ntal Coordina	tor			Approval Dat	e: 1/20/2016		Expiration I	Date: N/A	
						**			•		
E-mail Address: atrujillo@concho.com					Conditions of Approval: N/A				Attached		
								NAL		Anacheu []	
Date: Decer			one: 575-7	48-6940							
Attach Addi	tional Shee	ets If Necess	ary							2RP-3356	