## Received 1/18/2016 NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

				56	illia I (	c, 141VI 073	03				
			Rele	ease Notific	ation	n and Co	rrective A	ction			
						<b>OPERA</b>	ΓOR	☐ Initia	al Report	X	Final Report
						Contact Leslie Garvis					
Address 8(	01 Cherry	Street, Ste	1500, F	t. Worth, TX 76	Telephone No. 817-583-8730						
Facility Nar	ne Partiti	ion Tank Ba	ittery			Facility Typ	e Tank Batter	у			
Surface Owner BLM Mineral Owner						BLM API No. 30-015-38635					
				LOCA	TIO	N OF REI	EASE				
Unit Letter						h/South Line   Feet from the   East/West Line   County					
G	24 17S 31E 1395 Nor			Norti	th 2550		East	East Eddy			
Latitude Longitude											
NATURE OF RELEASE											
Type of Release Oil/produced water Volume of Release 5 bbls/10 bbls Volume Recovered 5 bbls/10 bbls											
Source of Release Gasket on water leg failed						Date and Hour of Occurre1262/15 0700 Date and Hour of Discovery 12/12/15 0700					
Was Immediate Notice Given?						If YES, To Whom?					
✓ Yes ☐ No ☐ Not Required						,					
By Whom? Leslie Garvis Was a Watercourse Reached?						Date and Hour 12/12/15 09:15  If YES, Volume Impacting the Watercourse.					
was a watercourse Reached?  ☐ Yes ☒ No						II YES, VO	nume impacting t	ne watercourse.			
If a Watercou	rse was Im	pacted, Descr	ibe Fully.	k							
N/A											
1471											
	- 1										
Describe Cause of Problem and Remedial Action Taken.*											
Gasket failed on water leg of heater treater and oil and produced water released into lined berm. Repair was made to line. Vac truck picked up											
standing fluid.											
			2 2 2 2								
Describe Area											
Produced water and oil was recovered from liner. Area was scraped.											
								nderstand that purs			
								eport" does not reli			
should their o	perations h	ave failed to a	adequately	investigate and r	emediat	e contaminati	on that pose a thre	eat to ground water	, surface wa	ater, hu	man health
				tance of a C-141	report d	oes not reliev	e the operator of i	responsibility for co	ompliance v	vith any	other
federal, state,	or local lav	ws and/or regu	ilations.				OIL COM	CEDVATION	DIVICIO	)NI	
	Andia	den.	1				OIL CONS	SERVATION	DIVISIO	JN	
Signature	jesuo.	Jak	6								
Printed Name: Leslie Garvis						Approved by Environmental Specialist:					
Title: Regulatory Coordinator						Annroyal Dat	e: 1/21/2016	Expiration	Data:	N/A	
Title.		@burnettoil.c	om					Expiration	Jaic.	- 1/11	
E-mail Addre	33.	woulletton.c	OIII			Conditions of	Approval:		Attached		
Date: 1/18/15 Phon 8.17-583-8730						N/A FINAL					