

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 1/29/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Unit #18H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-39999
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	28E	330	North	330	East	Eddy County, NM

Latitude N 32.04953° Longitude W 104.10235°

NATURE OF RELEASE

Type of Release: Oil and produced water	Volume of Release: 20 bbls oil, 5 bbls produced water	Volume Recovered: 15 bbls oil, 3 bbls produced water
Source of Release: Gasket failure on FWKO	Date and Hour of Occurrence 09/30/2015 @ 7:30 am	Date and Hour of Discovery 09/30/2015 @ 7:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 10/1/2015 @ 4:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a gasket failure on a FWKO. Vacuum trucks were dispatched to recover any standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The gasket sprayed out to the north and the west of the battery. Microblaze was applied to the pasture area. The spill site was sampled and a remediation plan was agreed on with NMOCD. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 12/15/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist:		
Title: Environmental Coordinator	Approval Date: 2/8/2016	Expiration Date: N/A	
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: January 25, 2016	Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-3358