

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 2/15/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Poker Lake Unit Battery #68 Battery located on same pad as Well #68	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No.30-015-25781

**LOCATION OF RELEASE**

Unit Letter B	Section 20	Township 24S	Range 31E	Feet from the 760	North/South Line North	Feet from the 2080	East/West Line East	County: Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------

Latitude N 32.207920 Longitude W 103.798160

**NATURE OF RELEASE**

Type of Release: Crude oil	Volume of Release: 5 Bbls.	Volume Recovered: 0
Source of Release: Pig launcher	Date and Hour of Occurrence: 5/7/13 Time unknown	Date and Hour of Discovery: 5/7/13 at 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Flanges leaked on a recently installed pig launcher on the facility oil transportation line. The flanges were tightened up.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 200 sq. ft of entrance road and caliche pad around the pig launcher was affected by release. The oil impacted soil was scraped up and stockpiled on site, clean caliche was put back into the excavation to allow entrance to the facility. A sampling event will be scheduled for the affected area to see if it meets the NMOCD requirements for remediation. Samples were collected and based on results BOPCO request no further action.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins		Approved by Environmental Specialist:	
Title: Environmental Supervisor		Approval Date: 2/15/2016	Expiration Date: N/A
E-mail Address: bblevins@basspet.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-15-16 Phone: 1-432-214-3704		FINAL	

\* Attach Additional Sheets If Necessary

2RP-1658