

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Federal 23 #13H	Facility Type	Well
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-41636

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	26	22S	31E					Eddy County, NM

Latitude N 32.36785°

Longitude W 103.75581°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	10 bbls oil, 10 bbls produced water	Volume Recovered	60 bbls, including approx.. 40 bbls of rain water
Source of Release	Stress/fatigue of a 4" poly production line	Date and Hour of Occurrence	08/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	08/25/2015 @ 2:35 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Stress/fatigue of a 4" poly line caused 10 bbls of oil and 10 bbls of produced water onto the ground. The line was repaired and a vacuum truck recovered 60 bbls of fluids, including approximately 40 bbls of rain water.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 30' on location. Remediation was completed according to the remediation plan approved by Mike Bratcher of NMOCD via email on 11/25/2015 and approved by Shelly Tucker of the BLM via email on 11/23/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist:	
Title: NM Environmental Advisor		Approval Date: 2/29/2016	Expiration Date: N/A
E-mail Address: casey_summers@oxy.com		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 2-23-16	Phone: (575) 513-8289		

* Attach Additional Sheets If Necessary

2RP-3269