

Received 3/4/2016

NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1602634997

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-JV-CVX-BS #028H; 2RP #3516	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42393
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 23	Township 24S	Range 30E	Feet from the 590	North/South Line North	Feet from the 1060	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.20902° Longitude: W 103.84621°

NATURE OF RELEASE

Type of Release: crude oil/produced water	Volume of Release: 8 bbls oil, 10 bbls PW	Volume Recovered: 5 bbls oil, 10 bbls PW
Source of Release: stuffing box	Date and Hour of Occurrence: 1/21/16 @ 8 am	Date and Hour of Discovery: 1/21/16 @ 8:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*

A stuffing box release occurred in the same area as spill dated 1-11-16. A vacuum truck was called to the location and recovered 15 barrels of oil and produced water.


Describe Area Affected and Cleanup Action Taken.*

A stuffing box release occurred in the same area as spill dated 1-11-16. The release impacted approximately 900 sq. ft. of well pad. The release area was remediated in conjunction with one other release; 2RP-3496. The contaminated soil was excavated and hauled to a state approved disposal facility and samples were collected. Based on laboratory analytical data and NMOCD approval the excavation has been backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:



Printed Name: Bradley Blevins

Approved by Environmental Specialist: MBratcher

Title: Assistant Remediation Foreman

Approval Date: 3/7/2016

Expiration Date: N/A

E-mail Address: bblevins@basspet.com

Conditions of Approval: N/A

Attached ☐

Date: 3-2-16

Phone: 432-214-3704

FINAL

* Attach Additional Sheets If Necessary

2RP-3516