

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505Form C-141  
Revised August 8, 2011Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Cimarex Energy	Contact: Christine Alderman
Address: 600 N Marienfield Ste 600 Midland Tx	Telephone No. 432-853-7059
Facility Name: Parkway State Com 4H	Facility Type: Production

Surface Owner: State	Mineral Owner: State	API No. 30-015-37504
----------------------	----------------------	----------------------

## LOCATION OF RELEASE

Unit Letter O	Section 15	Township 19S	Range 29E	Feet from the 330	North/South Line S	Feet from the 1650	East/West Line E	County EDDY
------------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude 32.654322 Longitude -104.059509

## NATURE OF RELEASE

Type of Release: Mixed Fluids	Volume of Release: 3bbls Crude 12bbls PW	Volume Recovered: 0bbls
Source of Release: Tank	Date and Hour of Occurrence: 8/11/14	Date and Hour of Discovery: 8/11/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Christine Alderman	Date and Hour: 8/11/14	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The well came in while stripping the flange and BOP over the string during work over. This caused a release of approximately 13bbls of oil and 12bbls of produced water. No fluid was recovered. Talon/LPE mobilized personnel to conduct an initial site assessment and soil sampling within the impacted area.

Describe Area Affected and Cleanup Action Taken.\*

Talon/LPE mobilized personnel to conduct an initial site assessment and perform soil sampling within the impacted area. Upon receipt of analytical results from the soil sampling event a work plan was generated and subsequently approved by NMOCD. The remediation took place to the scope laid out in the approved work plan. The area was backfilled and contoured to match the surrounding location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist:	
Title: EHS-Supervisor	Approval Date: 3/8/2016	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/7/16 Phone: 432-853-7059	FINAL	

\* Attach Additional Sheets If Necessary

2RP-2480