

Received 4/2/2015

NMOCD Artesia

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Artec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: OXY Permian	Contact: Christopher Jones
Address: 1502 W Commerce Dr.	Telephone No. 575-499-3337
Facility Name: Righthand Canyon 34 Fed Battery	Facility Type:
Surface Owner	Mineral Owner
API No. 30-015-32807	

**LOCATION OF RELEASE**

Unit Letter O	Section: 34	Township: 21S	Range 24E	Feet from the 1176	North/South Line S	Feet from the 2123	East/West Line E	County: Eddy
------------------	----------------	------------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	-----------------

Latitude 32.40178 Longitude -104.5229

Incorrect Location should be  
32.4315, -104.4941

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 8-10 BBLs Water	Volume Recovered: 0
Source of Release: Victrollic	Date and Hour of Occurrence: 1/10/2015	Date and Hour of Discovery: 1/10/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
4 inch Victrollic on water line came loose causing an impact an approximate 384 sq. ft. of ground area in battery area.		
Describe Area Affected and Cleanup Action Taken.*		
Safety & Environmental Solutions, Inc. submitted a plan of remediation to regulatory authorities on February 18, 2015 and was approved on 02-19-2015 and 02-23-2015 respectively by said authorities. Work was complete and final labs submitted on March 24, 2015.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <b>Chris Jones</b> <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o=us, email=ckjones00@yahoo.com, c=US Date: 2016.03.16 20:48:46 -05'00'</small>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name Christopher Jones:	Approved by Environmental Specialist:	
Title: HES Specialist	Approval Date: 3/16/2016	Expiration Date: N/A
E-mail Address: Christopher_jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-31-15 Phone: 575-499-3337	FINAL	

\* Attach Additional Sheets If Necessary

2RP-2790

HES Specialist

3-31-15